

# Improving stability for TCPM using boards that are not self-powered


Sebastian Reichel



COLLABORA

Open First


# USB-C Power Delivery (PD)




# USB PD implementations

- Handled by Port Controller
- Option 1: autonomously handled
  - USB Type-C Connector System Software Interface (UCSI)
  - (this setup is usually found on laptops)
- **Option 2: non-autonomously**
  - e.g. USB Type-C Port Controller Manager (TCPM)

# Radxa ROCK 5B USB-C setup



# USB PD Source Capability



COLLABORA

Open First

# USB PD Initialization

- Source Capability message is send multiple times
- After 5 sec source assumes device is not PD compliant
- If source receives PD message later: Error State
- Error recovery: Hard Reset
- Hard Reset involves disabling VBUS!

# Radxa ROCK 5B USB-C issue

- Boot process is relatively slow
  - DRAM Init, Trusted FW setup, U-Boot SPL, U-Boot, Load compressed kernel, decompress it, jump to it, boot to fusb302 driver probe
- specification compliant source will result in boot loop

# Solutions?

- Modify hardware design to use an autonomous controller
  - Too late, hardware is already on the market
- Make booting the kernel fast enough?
  - Unrealistic in lots of scenarios (network boot, debugging)
- Handle USB-C controller in firmware
  - firmware is right now SoC specific, but PD controller is board specific
  - requires sharing I2C interface between firmware and kernel
  - requires new protocol between firmware and kernel to share USB-C information



# Solutions?

- Add TCCPM to bootloader (U-Boot)
  - Landed upstream by now
  - U-Boot initializes PD
  - Linux re-initializes by doing a soft-reset (which does not remove VBUS)



# So problem fixed, all good?

- Unfortunately no
- A lot of USB-PD source equipment does not strictly follow the spec
  - For example many do not start to send source capability messages after a soft-reset
- TCPM strictly follows the state machine described in the specification
  - This may result in hard reset being requested by the kernel; effectively a hara-kiri operation

# Kernel Workarounds

- I introduced SNK\_WAIT\_CAPABILITIES\_TIMEOUT, which diverts from the spec (122968f8dda8)
- Print error on potential hara-kiri operation (876483a5a5bd)

# Ideas?

- Avoid hard reset and (ignore potentially broken USB-PD)?
  - Requires better detection of affected devices, currently relying on *self-powered*; property not being set for the connector DT node
- Hand over state from bootloader?
  - State machines are not exactly the same...
- ...



**Thank you!**



COLLABORA

**Open First**