



Contribution ID: 260

Type: **not specified**

3D Printing without the use of any slicer.

Tuesday, September 10, 2019 1:00 PM (30 minutes)

Currently to print an stl model in a 3D printer the same needs to be sliced first into a gcode to be understandable by a 3D printing software. In Linux we do not have any filter that can convert a stl code to a gcode. First we plan to discuss on what is the current scenario and then what can we do to fit in Linux.

Presenter: BASU, Aweek

Session Classification: Open Printing MC